



VEHICLE INSPECTION REPORT

NU12SWO

Mini Countryman 2.0 Cooper S D 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	25/05/2012	Body Style	Hatchback	MOT Due	19/01/2026
Year	2012	Service history	Yes	Gearbox	MANUAL
Mileage	103,815 Miles Warranted	Service documents	Service Book	Gears	6
Fuel Type	Diesel	Number of stamps	5	Doors	5
Colour	BLUE	Last service date	24/07/2025		
VIN	WMWZB720X0WN78494	Last service miles	103,600		

Last service 24/07/2025 at 103,600 miles- 5 services (3 main dealer) Book and print Engine tapping/vibration



Tyres

NSF	BUDGET	4.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	3.0mm
OSR	PIRELLI	3.0mm
Spare		

Features


- Cruise control
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- PAS
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Dented
Between 10mm + 30mm

No Image

14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Wheel osr
Scratched
Over 50mm




16: Door osr
Chipped
1 To 5



17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Door osf
Dented
Over 2 UpTo 10mm



19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Door Mirror Assy osf
 Scratched (Painted)
 Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	Fault
		Steering	OK