



VEHICLE INSPECTION REPORT

HV66YKS

Kia Sportage 1.6 GDi 1 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy



Details

Reg. date	28/11/2016	Body Style	Estate	Last service miles	136,771
Year	2016	Keys	2	MOT Due	Expired
Mileage	138,172 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	13		
VIN	U5YPG814LGL189818	Last service date	08/08/2025		

£100 ADDITIONAL FEE

EXPIRED MOT

Last Service - 08.08.2025 at 136771 miles (13 main dealer services)

oil light is on

EML light is on

Tyres

NSF	COMFORSER	3.0mm
NSR	BUDGET	3.0mm
OSF	COMFORSER	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
With Paint Damage



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Poor Previous Repair
Poor Paint



10: Bumper Rear
Scratched
Over 100mm Thru Paint




11: Boot Lid
Dented
Over 30mm



12: Wheel osr
Scratched
Up To 50mm



13: Qtr Panel osr
Chipped
1 To 5



14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




15: Roof
Dented
Over 30mm



16: Door osr
Poor Previous Repair
Poor Paint



17: Door osf
Chipped
1 To 5



18: Door osf
Scratched
Over 25mm Not Thru Paint



19: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



20: Wing osf
Dented
Over 2 UpTo 10mm

No Image



21: Wing osf
Scratched
Over 25mm Not Thru Paint

22: Wheel osf
Scratched
Over 50mm



23: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK