



VEHICLE INSPECTION REPORT

GJ63EOV

Hyundai IX35 1.7 CRDi SE 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	31/10/2013	Body Style	Estate	Last service miles	92,763
Year	2013	Keys	2	MOT Due	Expired
Mileage	102,949 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	3		
VIN	TMAJU81ULEJ494539	Last service date	21/08/2024		

£100 ADDITIONAL FEE EXPIRED MOT.

Last Service - 21.08.2024 at miles (services)

New Turbo Fitted 19.036.2024 @ 91269 miles Driver side window switches faulty

Gearbox faulty (reverse)

Tyres

NSF	RAPID	6.0mm
NSR	UNIROYAL	6.0mm
OSF	RAPID	6.0mm
OSR	UNIROYAL	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Partial leather seat trim
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos




1: Seat Base Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
Over 5mm



3: Bumper Front
Chipped
Multiple Chips



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsr
Dented
Between 10mm + 30mm



8: Qtr Panel nsr
Dented
Between 10mm + 30mm



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Dented
With Paint Damage



11: Roof
Dented
Over 30mm



12: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



13: Door osr
Chipped
Edge Chip



14: Door osf
Chipped
Edge Chip



15: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Poor	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	Fault	Radio	OK
		Steering	OK