

VEHICLE INSPECTION REPORT

LN15LDJ

Ford Fiesta 1.0 EcoBoost 125 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/03/2015	Body Style	Hatchback	Last service miles	96,258
Year	2015	Keys	1	MOT Due	02/02/2026
Mileage	98,469 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	RED	Number of stamps	2	Doors	5
VIN	WF0DXXGAKDFC79170	Last service date	06/06/2025		

Last service 06/06/2025 at 96,258 miles- 2 services Engine tapping

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	MAXXIS	4.0mm
OSR	LAUFENN	3.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Solid Paint
- ESP
- Remote central locking
- Cruise control
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- PAS
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wing nsf
Chipped
1 To 5




4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint




9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Poor Previous Repair
Poor Paint



11: Bumper Rear
Chipped
Multiple Chips



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Scratched
Over 25mm Thru Paint




14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osf
Dented
With Paint Damage



18: Screen Front
Chipped
UpTo 10mm



19: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



20: Wing osf
Chipped
1 To 5



21: Wheel of
Scratched
Over 50mm



22: Roof
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK