



VEHICLE INSPECTION REPORT

GP66FVD

Toyota Yaris 1.5 Hybrid Design 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	05/11/2016	Body Style	Hatchback	Last service miles	73,268
Year	2016	Keys	2	MOT Due	04/11/2025
Mileage	75,987 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Service Book	Gears	1
Colour	BLUE	Number of stamps	11	Doors	5
VIN	VNKKD3D350A285010	Last service date	07/08/2025		

Last Service - 07.08.2025 at 73268 miles (11 main dealer services)
Rough idle while starting

Tyres

NSF	YOKOHAMA	4.0mm
NSR	YOKOHAMA	4.0mm
OSF	YOKOHAMA	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Traction control
- Alloy wheels
- PAS
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Paint Flake

No Image



3: Wing nsf
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Up To 50mm



5: Door nsf
Poor Previous Repair
Poor Paint

6: Door nsr
Dented
Between 10mm + 30mm

No Image




7: Door nsr
Scratched
Over 25mm Not Thru Paint


8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Chipped
Multiple Chips



10: Bumper Rear
Scratched
Over 25mm Not Thru Paint




11: Boot Lid
Scratched
Over 25mm Not Thru Paint



12: Wheel osr
Scratched
Up To 50mm




13: Door osr
Chipped
1 To 5




14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Door osf
Chipped
1 To 5




16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wing osf
Scratched
Over 25mm Not Thru Paint



18: Wheel osf
Scratched
Over 50mm



19: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK