

VEHICLE INSPECTION REPORT

GV69NYW

Volkswagen T-Roc 1.5 TSI EVO SE 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE GRADE
		V5	Present		
Details					
Reg. date	16/01/2020	Body Style	Hatchback	Last service miles	31,847
Year	2020	Keys	2	MOT Due	21/01/2026
Mileage	35,841 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	4	Doors	5
VIN	WVGZZZA1ZLV058142	Last service date	17/01/2025		

£65 ADDITIONAL FEE.

Last service 17/01/2025at 31,847 miles- 4 services (3 main dealer) Abs ,traction control and steering light on dash

Tyres

NSF	RAPID	4.0mm	
NSR	BRIDGESTONE	2.0mm	
OSF	RAPID	4.0mm	
OSR	BRIDGESTONE	4.0mm	
Spare	<u> </u>		

Features

- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- · Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim


- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos












Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched Over 100mm Thru Paint



3: Wing nsf Chipped 1 To 5



4: Wheel nsf Scratched Over 50mm



5: Door nsf Chipped 1 To 5

No Image

6: Door nsf Scratched Over 25mm Not Thru Paint



7: Door nsr Chipped 1 To 5

No Image

8: Door nsr Scratched Over 25mm Not Thru Paint



9: Wheel nsr Scratched Up To 50mm



10: Qtr Panel nsr Scratched Over 25mm Thru Paint




11: Bumper Rear Poor Previous Repair Poor Paint

No Image

12: Boot Lid Scratched Over 25mm Not Thru Paint

No Image





14: Wheel osr Scratched Up To 50mm



15: Door osr Chipped 1 To 5

No Image

16: Door osr Scratched Over 25mm Not Thru Paint



17: Door osf Chipped 1 To 5



18: Wing osf Chipped 1 To 5



19: Wheel osf Scratched Up To 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	Fault