



VEHICLE INSPECTION REPORT

GU69WUK

Citroen Grand C4 Spacetourer 1.2 PureTech 130 Feel Plus 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	14/01/2020	Body Style	MPV	Last service miles	46,960
Year	2020	Keys	2	MOT Due	13/01/2026
Mileage	52,448 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	3		
VIN	VF73AHNS2KJ894661	Last service date	02/01/2025		

Last service 02/01/2025 at 46960 miles (3 main dealer services). Esp system faulty
Automatic braking system faulty
Service light is on

Tyres

NSF	TRIANGLE	Damaged
NSR	MICHELIN	5.0mm
OSF	TRIANGLE	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Partial leather seat trim
- Front parking sensor
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Tailgate
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Qtr Panel osr
Dented
With Paint Damage



13: Wheel osr
Corroded
Light



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
 Scratched
 Over 25mm Thru Paint



16: Wheel osr
 Scratched
 Over 50mm




17: Wing osf
 Scratched
 UpTo 25mm Thru Paint



18: Roof
 Dented
 Between 10mm + 30mm



19: Sill ns
 Dented
 Over 30mm



20: Tyre nsf
 Damaged
 Replace



21: Switches And Controls

Missing
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK