



VEHICLE INSPECTION REPORT

AU71KFF

Mazda CX-30 2.0 e-Skyactiv G MHEV SE-L Lux 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	05/02/2022	Body Style	Hatchback	Last service miles	33,952
Year	2022	Keys	2	MOT Due	04/02/2026
Mileage	37,398 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	3	Doors	5
VIN	JMZDM6WE600301213	Last service date	04/12/2024		

Last service 04/12/2024 at 33,952 miles- 3 services

Tyres


NSF	BRIDGESTONE	3.0mm
NSR	BRIDGESTONE	3.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BRIDGESTONE	2.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Up To 50mm


No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Chipped
1 To 5

No Image



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Up To 50mm

No Image

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Chipped
Multiple Chips

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

13: Boot Lid
Scratched
Over 25mm Not Thru Paint




14: Qtr Panel osr
Dented
2 Or Less UpTo 10mm




15: Wheel osr
Scratched
Up To 50mm




16: Door osr
Chipped
1 To 5



17: Door osf
Scratched
Over 25mm Not Thru Paint



18: Screen Front
Chipped
UpTo 10mm



19: Wing osf
Scratched
Over 25mm Not Thru Paint



20: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK