



VEHICLE INSPECTION REPORT

RX15VDA

Kia Rio 1.4 CRDi 3 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 03/03/2015

Year 2015

Mileage 137,848 Miles
Warranted

Fuel Type Diesel

Colour BLUE

VIN KNADN514LF6712252

Body Style Hatchback

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 8

Last service date 23/01/2024

Last service miles 117,377

MOT Due 26/01/2026

Gearbox MANUAL

Gears 6

Doors 5

£100 ADDITIONAL FEE

Last Service - 23.01.2024 at 117377 miles (8 services)

Eml on

Tyres

NSF BUDGET 4.0mm

NSR BUDGET 2.0mm

OSF BUDGET Worn

OSR BUDGET 2.0mm

Spare

Features


- Bluetooth connection
- Park assist camera
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image




4: Wheel nsf
Scratched
Over 50mm




5: Bumper Front
Insecure
Action Required



6: Wing nsf
Dented
With Paint Damage




7: Door Mirror Assy nsf
Broken
Replace



8: Door nsf
Chipped
Multiple Chips



9: Door nsr
Dented
2 Or Less UpTo 10mm



10: Door nsr
Scratched
Over 25mm Not Thru Paint




11: Qtr Panel nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image



15: Boot Lid
Scratched
Over 25mm Not Thru Paint


16: Qtr Panel osr
Dented
With Paint Damage



17: Wheel osr
Scratched
Up To 50mm



18: Door osr
Chipped
Multiple Chips



19: Door osf
Chipped
1 To 5

No Image

20: Door osf
Scratched
Over 25mm Not Thru Paint



21: Wheel osf
Scratched
Over 50mm



22: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK