



VEHICLE INSPECTION REPORT

OV17YBS

Mercedes-Benz A Class A200d SE Executive 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/06/2017	VIN	WDD1760082V194919	Number of stamps	1
Year	2017	Body Style	Hatchback	Last service date	19/01/2022
Mileage	121,011 Miles Warranted	Keys	1	Last service miles	52,587
Fuel Type	Diesel	Service history	Yes	MOT Due	27/08/2026
Colour	BLACK	Service documents	Printout	Doors	5

Last service 19/01/2022 at 52,587 miles- 1 main dealer service Gearbox faulty
Rear suspension knocking

Tyres

NSF	BUDGET	5.0mm
NSR	MAXXIS	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	BUDGET	5.0mm
Spare		


Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Leather seat trim


Photos



Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wheel nsf
Scratched
Over 50mm



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Dented
With Paint Damage



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel nsr
Rusted
Over 5mm



8: Bumper Rear
Chipped
Multiple Chips



9: Tailgate
Scratched
Over 25mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Chipped
Edge Chip



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Chipped
Edge Chip



14: Wheel osf
Scratched
Up To 50mm



15: Wing osf
Chipped
1 To 5



16: Roof
Dented
Over 30mm



17: Seat Base Cover osf
Scuffed
Over 25mm



18: Bumper Front
Cracked
Over 25mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK