



VEHICLE INSPECTION REPORT

VK13NHZ

Nissan Qashqai 1.6 dCi 360 5dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/05/2013	Body Style	Hatchback	Last service miles	84,011
Year	2013	Keys	2	MOT Due	Expired
Mileage	103,934 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	8	Doors	5
VIN	SJNFEAJ10U2770073	Last service date	21/05/2022		

Last Service - 21.05.2022 at 84001 miles (8 services) Eml on

Tyres


NSF	BUDGET	Worn
NSR	ROYALBLACK	3.0mm
OSF	RAPID	Worn
OSR	ROYALBLACK	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Audio remote control
- Electric sunroof
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Digital radio
- Fixed panoramic glass roof
- Folding rear seats
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Park assist camera
- Telephone
- Body coloured bumpers
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Trip computer
- Electric door mirrors
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Poor Previous Repair
Poor Colour



3: Screen Front
Chipped
UpTo 10mm



4: Wheel osf
Scratched
Over 50mm



5: Door osf
Dented
With Paint Damage



6: Door osr
Dented
With Paint Damage



7: Wheel osr
Scratched
Over 50mm



8: Qtr Panel osr
Poor Previous Repair
Poor Paint



9: Boot Lid
Poor Previous Repair
Poor Paint




10: Bumper Rear
Poor Previous Repair
Paint Flake



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Poor Previous Repair
Poor Paint



13: Roof
Scratched
Over 25mm Not Thru Paint



14: Door nsr
Chipped
1 To 5

No Image

15: Door nsr
Scratched
Over 25mm Not Thru Paint

No Image

16: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image

17: Wing nsf
Scratched
Over 25mm Not Thru Paint



18: Wheel nsf
Scratched
Over 50mm

No Image

19: Tyre nsf
Worn
Replace

No Image

20: Tyre osf
Worn
Replace

No Image

No Image

21: Tyre nsf
Worn
Replace

22: Tyre osf
Worn
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		