



VEHICLE INSPECTION REPORT

AK69NJE

Volkswagen Tiguan 1.5 TSi EVO 150 Match 5dr

Cat: S		Inspection		Vehicle		nama GRADE 4	
Serious Damage?	No	VAT	Margin				
		V5	Present				
Details							
Reg. date	18/12/2019	Body Style	Estate	Last service miles	70,697		
Year	2019	Keys	1	MOT Due	04/08/2026		
Mileage	82,298 Miles Warranted	Service history	Yes	Gearbox	MANUAL		
Fuel Type	Petrol	Service documents	Printout	Gears	6		
Colour	GREY	Number of stamps	2				
VIN	WVGZZZ5NZLW337601	Last service date	02/01/2025				

Category S Insurance Loss. Vehicle Structurally Damaged But Repairable-Insurer Decided Not to Repair.
£100 ADDITIONAL FEE.
Last service 02/01/2025 at 70697 miles (2 services). Oil service due message display

Tyres		
NSF	PIRELLI	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	HANKOOK	1.0mm
OSR	HANKOOK	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Poor Previous Repair
Poor Paint



6: Door nsr
Poor Previous Repair
Poor Paint



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Door osr
Dented
2 Or Less UpTo 10mm



9: Door osf
Chipped
Edge Chip



10: Wheel osf
Scratched
Up To 50mm



11: Wing osf
Poor Previous Repair
Rippled UpTo 30%



12: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK