



46 Brampton Road  
Eastbourne  
BN229BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**WJ67NHB**

## Peugeot 3008 1.6 BlueHdi 120 GT Line 5dr EAT6

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	26/10/2017	Keys	2	CAP Clean	£6,925.00
Year	2017	Service history	Yes	CAP Average	£6,100.00
Mileage	117,177 Miles Warranted	Service documents	Service Book	CAP Below	£5,250.00
Fuel Type	Diesel	Number of stamps	8	Gearbox	AUTOMATIC
Colour	RED	Last service date	17/07/2024	Gears	6
VIN	VF3MCBHZWHS278271	Last service miles	109,679	Doors	5
Body Style	Hatchback	MOT Due	06/08/2025		

£65 ADDITIONAL FEE TIMING BELT CHANGED 30/04/2024 Last service 17/07/2024 @ 109679 miles (9 SERVICES 7 MAIN DEALER) book & print

### Tyres

NSF	MICHELIN	3.0mm
NSR	MICHELIN	2.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	3.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Heated front seat
- Trip computer
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Passenger airbag
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint





3: Screen Front  
Chipped  
UpTo 10mm



4: Door nsf  
Chipped  
1 To 5




5: Wheel nsf  
Corroded  
Light



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Bumper Rear  
Chipped  
Multiple Chips

No Image

9: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



10: Boot Lid  
Chipped  
1 To 5

No Image

11: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



12: Wheel osr  
Corroded  
Light

No Image

13: Door osr  
Scratched  
Over 25mm Not Thru Paint



14: Door osf  
Chipped  
1 To 5



15: Wheel of  
Corroded  
Light

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK