



VEHICLE INSPECTION REPORT

HY16ZTM

Mazda 6 2.0 Sport Nav 4dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/03/2016	Body Style	Saloon	Last service miles	68,752
Year	2016	Keys	2	MOT Due	23/02/2026
Mileage	77,173 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	6	Doors	4
VIN	JMZGJ627671345242	Last service date	30/08/2024		

Last service 30/08/2024 at 68,752 miles- 6 services (3 main dealer) Engine rattling
Battery management system malfunction
I-stop light flashing

Tyres

NSF	FARROAD	5.0mm
NSR	BUDGET	6.0mm
OSF	ROYALBLACK	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips




3: Wheel nsf
Dented
UpTo 30mm (Alloy)



4: Screen Front
Chipped
Over 10mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
Over 30mm



7: Door nsr
Scratched
Over 25mm Thru Paint




8: Door nsr
Dented
Between 10mm + 30mm



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Boot Lid
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Dented
Over 30mm



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Poor Previous Repair
Poor Paint



16: Door osf
Scratched
UpTo 25mm Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Chipped
1 To 5



19: Roof
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK