



# VEHICLE INSPECTION REPORT

**RJ13UVL**

## Honda Civic 1.6 i-DTEC ES 5dr

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |



### Details

|           |                           |                   |              |                    |            |
|-----------|---------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 11/07/2013                | Body Style        | Hatchback    | Last service miles | 82,208     |
| Year      | 2013                      | Keys              | 2            | MOT Due            | 13/11/2025 |
| Mileage   | 93,951 Miles<br>Warranted | Service history   | Yes          | Gearbox            | MANUAL     |
| Fuel Type | Diesel                    | Service documents | Service Book | Gears              | 6          |
| Colour    | SILVER                    | Number of stamps  | 7            | Doors              | 5          |
| VIN       | SHHFK3770DU207086         | Last service date | 22/11/2022   |                    |            |

Last service 22/11/2022 at 82,208 miles- 7 services (4 main dealer) Engine tapping

### Tyres


|       |        |       |
|-------|--------|-------|
| NSF   | BUDGET | 4.0mm |
| NSR   | MAXXIS | 4.0mm |
| OSF   | BUDGET | 3.0mm |
| OSR   | MAXXIS | 4.0mm |
| Spare |        |       |

## Features


- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Central locking

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Poor Previous Repair  
Poor Paint





3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Dented  
Over 30mm



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Boot Lid  
Chipped  
1 To 5



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



12: Wheel osr  
Scratched  
Up To 50mm



13: Door osr  
Dented  
Over 30mm



14: Door osf  
Dented  
With Paint Damage





15: Roof  
Poor Previous Repair  
Paint Flake



16: Wheel osf  
Scratched  
Over 50mm



17: Wing osf  
Dented  
Over 2 UpTo 10mm



18: Screen Front  
Chipped  
UpTo 10mm

Interior

Carpet Condition                      Average  
Seat Condition                        Average

Upholstery Condition                Average  
Odour                                      No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

|                |       |                                                |    |
|----------------|-------|------------------------------------------------|----|
| Engine Runs    | Fault | Gearbox 1st and Reverse Test                   | OK |
| Brakes         | OK    | Clutch Slip Test from Static                   | OK |
| Turbo Boosting | OK    | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake  | OK    | No Excessive Smoking                           | OK |

|                          |    |                                     |    |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated    | OK | Oil warning light illuminated       | OK |
| Airbag light illuminated | OK | DPF light illuminated               | OK |
| ABS light illuminated    | OK | Service indicator light illuminated | OK |
| Windows                  | OK | Radio                               | OK |
|                          |    | Steering                            | OK |