



46 Brampton Road  
Eastbourne  
BN229BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**GU20YNF**

## Ford Mondeo 2.0 EcoBlue 190 ST-Line Edition 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	19/06/2020	Keys	2	CAP Average	£9,975.00
Year	2020	Service documents	Service Book	CAP Below	£8,875.00
Mileage	78,769 Miles Warranted	Number of stamps	6	Gearbox	AUTOMATIC
Fuel Type	Diesel	Last service date	21/06/2024	Gears	8
Colour	BLUE	Last service miles	65,557	Doors	5
VIN	WF0EXXWPCELA34913	MOT Due	20/06/2025		
Body Style	Hatchback	CAP Clean	£11,050.00		

£65 ADDITIONAL FEE Last service 21/06/2024 @ 65557 miles (6 MAIN DEALER SERVICES)

### Tyres

NSF	ACCELERA	4.0mm
NSR	PIRELLI	3.0mm
OSF	ACCELERA	3.0mm
OSR	PIRELLI	3.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Climate control
- Cruise control
- PAS
- Telephone
- Digital radio
- LED headlights
- Electrically adjustable drivers seat
- Front electric windows
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Front head restraints
- Rear headrests
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Space saver spare wheel
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Audio remote control
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint





3: Wing osf  
Chipped  
1 To 5



4: Wheel osf  
Scratched  
Over 50mm



5: Door osf  
Dented  
With Paint Damage



6: Door osr  
Chipped  
1 To 5




7: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



8: Wheel osr  
Scratched  
Up To 50mm



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



No Image

10: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



No Image

11: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



No Image

12: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



13: Wheel nsr  
Scratched  
Over 50mm



14: Door nsf  
Chipped  
1 To 5





15: Door nsf  
Chipped  
1 To 5



16: Wing nsf  
Chipped  
1 To 5



17: Wheel nsf  
Scratched  
Over 50mm

**Interior**

**Carpet Condition**                    -  
**Seat Condition**                    -

**Upholstery Condition**           -  
**Odour**                                    -

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK