



VEHICLE INSPECTION REPORT

GF61RHJ

Nissan Qashqai 1.6 dCi Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/11/2011	Body Style	Hatchback	Last service miles	110,513
Year	2011	Keys	2	MOT Due	05/12/2025
Mileage	144,494 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	10	Doors	5
VIN	SJNFENJ10U2424728	Last service date	23/04/2022		

£50 ADDITIONAL FEE

Last service 23/04/2022 at 110,513 miles- 10 services (9 main dealer) book and print Eml on and suspension knock

Tyres



NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos




1: Bumper Front
Hole
Over 25mm



2: Bonnet
Dented
With Paint Damage



3: Wing osf
Chipped
1 To 5



4: Wing osf
Scratched
Over 25mm Not Thru Paint



5: Wheel osf
Scratched
Over 50mm



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door osr
Dented
With Paint Damage



8: Qtr Panel osr
Dented
Between 10mm + 30mm

No Image



9: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

10: Wheel osr
Scratched
Over 50mm



11: Bumper Rear
Poor Previous Repair
Poor Paint



12: Boot Lid
Dented
Over 30mm



13: Qtr Panel nsr
Chipped
1 To 5

No Image

14: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




15: Wheel nsr
Scratched
Over 50mm



16: Door nsr
Dented
With Paint Damage



17: Door nsf
Chipped
1 To 5



18: Door nsf
Scratched
Over 25mm Not Thru Paint



19: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



20: Wing nsf
Chipped
1 To 5

No Image



21: Wing nsf
Scratched
Over 25mm Not Thru Paint

22: Wheel nsf
Scratched
Over 50mm



23: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		