



VEHICLE INSPECTION REPORT

SE12JYF

Nissan Qashqai 1.6 [117] N-Tec+ 5dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/07/2012	Body Style	Hatchback	Last service miles	51,988
Year	2012	Keys	2	MOT Due	25/06/2026
Mileage	148,743 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	3	Doors	5
VIN	SJNFAAJ10U2591410	Last service date	26/08/2017		

Last service 26/08/2017 at 51988 miles (3 services (1 main dealer). Possible clutch fault while pulling away in first and tapping engine

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	4.0mm
OSR	TOYO	2.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Fixed panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wing nsf
Chipped
Multiple Chips



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Poor Previous Repair
Poor Paint



6: Door nsr
Poor Previous Repair
Poor Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Chipped
1 To 5



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Bumper Rear
Scratched
Over 25mm Not Thru Paint




11: Other
N/A
N/A



12: Boot Lid
Dented
Over 30mm



13: Qtr Panel osr
Chipped
1 To 5



14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Wheel osf
Scratched
Over 50mm




16: Door osf
Chipped
Multiple Chips



17: Door osf
Dented
With Paint Damage



18: Wing osf
Chipped
1 To 5



19: Wing osf
Scratched
Over 25mm Not Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Seat Base Cover osf
Torn
Over 3mm

22: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		