



VEHICLE INSPECTION REPORT

YH11EZG

Mini Hatchback 1.6 Cooper D 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	01/06/2011	VIN	WMWSW32020T211914	Gearbox	MANUAL
Year	2011	Body Style	Hatchback	Gears	6
Mileage	118,665 Miles Warranted	Keys	1	Doors	3
Fuel Type	Diesel	Service history	None		
Colour	BLACK	MOT Due	30/09/2026		

No service history. Service due message displayed

Noisy suspension

Engine tapping

Smoking

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Central locking
- Cruise control
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Rear airbags
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Partial leather seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Dented
2 Or Less UpTo 10mm



6: Door nsf
Chipped
1 To 5



7: Qtr Panel nsr
Dented
Between 10mm + 30mm



8: Qtr Panel nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
Up To 25mm Thru Paint



11: Qtr Panel osr
Dented
Over 30mm



12: Wheel osr
Scratched
Over 50mm



13: Door osf
Poor Previous Repair
Rippled UpTo 30%



14: Roof
Dented
2 Or Less UpTo 10mm



15: Roof
Chipped
1 To 5



16: Wheel osf
Scratched
Over 50mm



17: Screen Front
Chipped
UpTo 10mm



18: Bonnet
Dented
Between 10mm + 30mm



19: Switches And Controls
Broken
Replace



20: Roof Lining
Soiled
Light

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK