



# VEHICLE INSPECTION REPORT

RO18MVD

## Land Rover Discovery Sport 2.0 TD4 180 HSE Black 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	05/04/2018	Body Style	Estate	MOT Due	14/04/2026
Year	2018	Keys	2	CAP Clean	£8,350.00
Mileage	92,315 Miles Warranted	Service history	Yes	CAP Average	£7,350.00
Fuel Type	Diesel	Service documents	Printout	CAP Below	£6,325.00
Colour	GREY	Last service date	11/04/2025	Gearbox	AUTOMATIC
VIN	SALCA2AN4JH767166	Last service miles	91,746	Gears	9

£65 ADDITIONAL FEE Last service 11/04/2025 @ 91746 miles (6 SERVICES 1 MAIN DEALER)

### Tyres

NSF	MAXXIS	4.0mm
NSR	PIRELLI	Worn
OSF	MAXXIS	3.0mm
OSR	PIRELLI	2.0mm
Spare		

### Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Trip computer
- Electric door mirrors
- Full size spare wheel
- Electrically adjustable passenger seat
- Front head restraints
- Rear headrests
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Service indicator
- Audio remote control
- Electric sunroof
- Air conditioning
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Auxiliary input socket
- Fixed panoramic glass roof
- Climate control
- Front armrest
- Rear armrest
- ABS
- Traction control
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Telephone
- Digital radio
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

### Photos





## Condition Check



## Damage Photos



1: Boot Lid  
Chipped  
1 To 5



2: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



No Image

No Image


3: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

4: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



5: Wheel nsr  
Scratched  
Up To 50mm

6: Door nsr  
Dented  
2 Or Less UpTo 10mm



7: Door nsf  
Chipped  
1 To 5

8: Door nsr  
Scratched  
Over 25mm Not Thru Paint

No Image



9: Door nsf  
Scratched  
Over 25mm Not Thru Paint

10: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Not Thru Paint



11: Wing nsf  
Scratched  
Over 25mm Thru Paint



12: Wheel nsf  
Scratched  
Up To 50mm



13: Bonnet  
Chipped  
1 To 5



14: Bumper Front  
Scratched  
Over 100mm Thru Paint





15: Wheel osf  
Scratched  
Up To 50mm



16: Wing osf  
Chipped  
1 To 5




17: Door osf  
Chipped  
Multiple Chips



18: Door osr  
Chipped  
1 To 5



19: Wheel osr  
Scratched  
Up To 50mm



20: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

No Image

21: Tyre nsr  
Worn  
Replace

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		