

46 Brampton Road Eastbourne BN229BN 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT



Audi A1 1.4 TFSI Sport 5dr S Tronic

Inspection		Vehicle		nama
No	VAT	Margin		
	V5	Present		
05/05/2015	Body Style	Hatchback	Last service miles	85,976
2015	Keys	2	MOT Due	05/03/2026
86,120 Miles	Service history	Yes	Gearbox	SEMI AUTO
Warranted	Service documents	Printout	Gears	7
Petrol	Number of stamps	6	Doors	5
WHITE	· · · · ·	23/04/2025		
WAUZZZ8X2FB013054				
	05/05/2015 2015 86,120 Miles Warranted Petrol WHITE	No VAT 05/05/2015 Body Style 2015 Keys 86,120 Miles Service history Warranted Service documents Petrol Number of stamps WHITE Last service date	NoVATMarginV5Present05/05/2015Body StyleHatchback2015Keys286,120 Miles WarrantedService historyYesService documentsPrintoutPetrolNumber of stamps6WHITELast service date23/04/2025	NoVATMarginV5Present05/05/2015Body StyleHatchbackLast service miles2015Keys2MOT Due86,120 Miles WarrantedService historyYesGearboxService documentsPrintoutGearsPetrolNumber of stamps6DoorsWHITELast service date23/04/2025

£65 ADDITIONAL FEE.

Last Service - 23.04.2025 at 85976 miles (6 main dealer services) Abs and traction control light on

Tyres			
NSF	BUDGET	4.0mm	
NSR	BUDGET	4.0mm	
OSF	BUDGET	4.0mm	
OSR	BUDGET	4.0mm	
Spare			

Features

Bluetooth connection Front parki Steering wheel mounted controls Telephone

- Digital radio
- Climate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

Front parking sensor

Body coloured bumpers

Front electric windows

Rear headrests

Drivers airbag

Central locking

•

•

- PASTrip computer
 - Electric door mirrors
 - Front head restraints
 - Solid Paint
 - · Isofix child seat anchor points
 - Remote central locking
- Rear parking sensor
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos























Condition Check



Damage Photos







2: Bumper Front Scratched Over 100mm Thru Paint



3: Wheel osf Scratched Over 50mm



5: Door osf Chipped 1 To 5





6: Qtr Panel osr Dented 2 Or Less UpTo 10mm



7: Wheel osr Scratched Over 50mm



8: Bumper Rear Scratched 25 to 100mm Thru Paint


No Image

No Image

9: Bumper Rear Scratched Over 25mm Not Thru Paint



11: Door nsr Scratched Over 25mm Not Thru Paint





12: Wheel nsr Scratched Up To 50mm



13: Door nsf Chipped 1 To 5

Interior

No Image

14: Wing nsf Scratched Over 25mm Not Thru Paint

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	OK