

VEHICLE INSPECTION REPORT

GJ19UYT

Kia Ceed 1.0T GDi ISG GT-Line 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE
		V5	Present		
Details					
Reg. date	15/03/2019	Body Style	Hatchback	Last service miles	79,830
Year	2019	Keys	2	MOT Due	10/01/2026
Mileage	84,681 Miles Warranted	Service history	Yes	Gearbox	MANUAL
		Service documents	Service Book	Gears	6
Fuel Type	Petrol	Number of stamps	7	Doors	5
Colour	BLUE	Last service date	25/06/2025		
VIN	U5YH6511LKL044924				

£65 ADDITIONAL FEE

Last Service - 25.06.2025 at 79830 miles (7 main dealer services)

NSF	BUDGET	Worn	
NSR	BUDGET	4.0mm	
OSF	BUDGET	2.0mm	
OSR	BUDGET	4.0mm	
Spare			

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control · Alloy wheels
- · Cruise control
- PAS
- Air conditioning
- Front head restraints
- Metallic PaintIsofix child seat anchor points
- Central locking

- Heated front seat
- Rear parking sensorDigital radio
- Climate control
- Height adjustable drivers seat3x3 point rear seat belts


- Passenger airbagRemote central locking
- · Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbagsPartial leather seat trim

Photos











Condition Check



Damage Photos



1: Handle Inner osf Damaged Replace



2: Bonnet Chipped 1 To 5




3: Bumper Front Cracked UpTo 25mm



4: Wing nsf Chipped 1 To 5

No Image





6: Wheel nsf Scratched Over 50mm



7: Door nsf Dented Over 30mm



8: Door nsr Chipped 1 To 5

No Image

9: Door nsr Scratched Over 25mm Not Thru Paint



11: Qtr Panel nsr Chipped 1 To 5



13: Bumper Rear Scratched 25 to 100mm Thru Paint



10: Wheel nsr Scratched Over 50mm

No Image

12: Qtr Panel nsr Scratched Over 25mm Not Thru Paint

No Image

14: Bumper RearScratchedOver 25mm Not Thru Paint

No Image

15: Boot Lid Scratched Over 25mm Not Thru Paint



17: Wheel osr Scratched Over 50mm



16: Qtr Panel osr Dented Over 30mm



18: Door osr Dented Over 2 UpTo 10mm

No Image

19: Door osr Scratched Over 25mm Not Thru Paint



20: Door osf Dented 2 Or Less UpTo 10mm



21: Wing osf Chipped 1 To 5



22: Wheel osf Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
	OK	Service indicator light illuminated	
Airbag light illuminated		Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK