



VEHICLE INSPECTION REPORT

GU14BZT

Peugeot 2008 1.6 e-HDi Allure 5dr EGC

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	05/03/2014	Body Style	Hatchback	Last service miles	64,578
Year	2014	Keys	2	MOT Due	02/03/2026
Mileage	103,519 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	8	Doors	5
VIN	VF3CU9HP8EY009131	Last service date	25/01/2021		

Last Service - 25.01.2021 at 64578 miles (8 services 7 main dealer services) Possible gearbox faulty

Tyres


NSF	BUDGET	5.0mm
NSR	BLACKLION	5.0mm
OSF	BUDGET	5.0mm
OSR	BLACKLION	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Rear electric windows
- Metallic Paint
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bumper Front
Chipped
1 To 5



3: Bumper Front Moulding
Broken
Replace



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Dented
Over 30mm



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
Over 30mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Dented
Between 10mm + 30mm



14: Door osf
Dented
Between 10mm + 30mm



15: Door osf
Chipped
Edge Chip



16: Wing osf
Dented
Between 10mm + 30mm



17: Wheel osf
Scratched
Over 50mm



18: Flasher Side Repeater os
Broken
Replace

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK		