



VEHICLE INSPECTION REPORT

NX69UZU

Skoda Kodiaq 2.0 TDI 190 Sport Line 4x4 5dr DSG [7 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/10/2019	Body Style	Estate	Last service miles	62,588
Year	2019	Keys	2	MOT Due	19/11/2025
Mileage	106,576 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	BLUE	Number of stamps	4		
VIN	TMBMK7NS9L8021823	Last service date	05/07/2022		

£65 ADDITIONAL FEE

Last service 05/07/2022 at 62,588 miles- 4 main dealer services Add blue message displayed

Tyres

NSF	PIRELLI	6.0mm
NSR	KUMHO	5.0mm
OSF	PIRELLI	6.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
Multiple Chips



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Scratched
UpTo 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Door nsr
Dented
Between 10mm + 30mm



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Dented
Between 10mm + 30mm



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Dented
Between 10mm + 30mm



17: Qtr Panel osr
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK