



VEHICLE INSPECTION REPORT

GP10DNF

Peugeot 5008 2.0 HDi 163 Exclusive 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/08/2010	Body Style	MPV	Last service miles	106,527
Year	2010	Keys	2	MOT Due	07/06/2026
Mileage	112,774 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Electronic / Online	Gears	6
Colour	SILVER	Number of stamps	2		
VIN	VF30ERHHAAS201499	Last service date	29/07/2024		

Last Service - 29.07.2024 at 106527 miles (2 confirmed services at SivTech)
Oil level warning message displayed
Overheating
Knocking from rear suspension

Tyres


NSF	KUMHO	5.0mm
NSR	NEXEN	5.0mm
OSF	KUMHO	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Front fog lights
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Cruise control
- PAS
- Body coloured bumpers
- Full size spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Leather seat trim
- Heated front seat
- Rear wiper
- Fixed panoramic glass roof
- Towbar
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Parking Sensor Front
Missing
Replace



3: Bumper Front Moulding
Broken
Replace



4: Bumper Front
Dented
With Paint Damage



5: Wheel nsf
Scratched
Over 50mm



6: Sill ns
Dented
Over 30mm



7: Wing nsf
Scratched
UpTo 25mm Thru Paint



8: B Post ns
Scratched
UpTo 25mm Thru Paint



9: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



10: Door nsf
Dented
Over 30mm



11: Door nsr
Dented
Over 30mm



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



14: Bumper Rear
Hole
Over 25mm



15: Tailgate
Dented
Over 30mm



16: Qtr Panel osr
Dented
Over 30mm



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Scratched
UpTo 25mm Thru Paint




19: Door osf
Dented
Between 10mm + 30mm



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
Scratched
UpTo 25mm Thru Paint



22: Screen Front
Cracked
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK