



VEHICLE INSPECTION REPORT

GD64ZFR

Skoda Rapid Spaceback 1.2 TSI 105 SE Tech 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	07/02/2015	Body Style	Hatchback	Last service miles	10,620
Year	2015	Keys	2	MOT Due	08/02/2026
Mileage	125,692 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	1	Doors	5
VIN	TMBFN6NHXF4518664	Last service date	19/12/2015		

£65 ADDITIONAL FEE

LAST SERVICE 19/12/15 @ 10,620 MILES (1 MAIN DEALER) PRINT

Tyres

NSF	HANKOOK	3.0mm
NSR	HANKOOK	3.0mm
OSF	HANKOOK	2.0mm
OSR	HANKOOK	3.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Dented
2 Or Less UpTo 10mm



2: Door osf
Scratched
UpTo 25mm Thru Paint



3: Door osf
Chipped
Edge Chip



4: Door osr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




7: Bumper Rear Moulding
Broken
Replace



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



10: Door nsr
Scratched
Over 25mm Not Thru Paint




11: Wing nsf
Scratched
Over 25mm Not Thru Paint



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Bonnet
Chipped
1 To 5



14: Door nsf
Dented
With Paint Damage

No Image

15: Wheel nsf
Scratched
Over 50mm

No Image

16: Wheel nsr
Scratched
Over 50mm

No Image

17: Wheel osr
Scratched
Over 50mm

No Image

18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK