



VEHICLE INSPECTION REPORT

EG15BLN

Ford Grand C-Max 2.0 TDCi Titanium X 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/07/2015	Keys	2	CAP Clean	£3,475.00
Year	2015	Service history	Yes	CAP Average	£2,950.00
Mileage	116,129 Miles Warranted	Service documents	Service Book	CAP Below	£2,400.00
Fuel Type	Diesel	Number of stamps	8	Gearbox	MANUAL
Colour	SILVER	Last service date	17/01/2025	Gears	6
VIN	WF0WXXGCEWFS45443	Last service miles	88,056		
Body Style	MPV	MOT Due	28/07/2025		

£65 ADDITIONAL FEE Last service 17/01/2025 @ 88056 miles (8 SERVICES 7 MAIN DEALER) Rear bumper misaligned and child lock service malfunction

Tyres




NSF	UNIROYAL	3.0mm
NSR	TORQUE	2.0mm
OSF	UNIROYAL	3.0mm
OSR	TRIANGLE	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Digital radio
- Electric sunroof
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Radio/CD
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Traction control
- Leather seat trim
- PAS
- Trip computer
- Body coloured bumpers
- Front fog lights
- Front electric windows
- Rear headrests
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Audio remote control
- Electric door mirrors
- Air conditioning
- Front head restraints
- Metallic Paint
- Passenger airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Screen Front
Chipped
UpTo 10mm



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm




5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsr
Chipped
1 To 5




7: Wheel nsr
Corroded
Light



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



11: Door osr
Scratched
Over 25mm Not Thru Paint



12: Door osf
Dented
Over 2 UpTo 10mm



13: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK