



VEHICLE INSPECTION REPORT

GY59EEZ

Volvo XC60 D5 [205] SE Lux Premium 5dr AWD Geartronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/12/2009	Body Style	Estate	Last service miles	85,878
Year	2009	Keys	2	MOT Due	13/10/2026
Mileage	94,117 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	9		
VIN	YV1DZ7046A2086471	Last service date	26/09/2024		

£65 ADDITIONAL FEE. Last service 26/09/2024 at 85878 miles (9 services (3 main dealer). Book & print. Electric boot fault and headlamp aim failure

Tyres

NSF	NEXEN	2.0mm
NSR	PIRELLI	3.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Leather seat trim
- Cruise control
- Audio remote control
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels
- PAS
- Radio/CD
- Climate control
- Front electric windows
- Rear headrests
- Curtain airbags
- Central locking
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Dented
With Paint Damage



3: Wheel nsf
Scratched
Over 50mm



4: Bumper Front
Cracked
UpTo 25mm



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
With Paint Damage



7: Wheel nsr
Scratched
Over 50mm




8: Qtr Panel nsr
Dented
With Paint Damage



9: Bumper Rear
Scratched
Over 100mm Thru Paint




10: Boot Lid
Scratched
UpTo 25mm Thru Paint



11: Boot Lid
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel osr
Dented
Between 10mm + 30mm



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



14: Wheel osr
Scratched
Up To 50mm



15: Door osr
Chipped
1 To 5

No Image



17: Door osf
Dented
2 Or Less UpTo 10mm

No Image



19: Door Mirror Assy osf
Broken
Replace



20: Wing osf
Chipped
1 To 5



21: Wheel osf
Scratched
Over 50mm



22: Screen Front
Chipped
UpTo 10mm



23: Door Pad osf
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK