

VEHICLE INSPECTION REPORT

GX22USD

MG Mg Hs EXCITE

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE.
		V5	Present		
Details					
Reg. date	29/03/2022	Keys	2	CAP Clean	£11,350.00
Year	2022	Service history	Yes	CAP Average	£10,200.00
Mileage	30,744 Miles Warranted	Service documents	Service Book	CAP Below	£9,000.00
		Number of stamps	3	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	04/03/2025	Gears	6
Colour	WHITE	Last service miles	30,232		
VIN	LSJA24U92MN160662	MOT Due	29/04/2026		
Body Style	Estate		20,0 .,2020		

£65 ADDITIONAL FEE. Last Service: 04/03/2025 at 30232 miles. (3 services)

_	-			
	1/	r	0	c
	v		┖	-

NSF	MICHELIN	2.0mm	
NSR	MICHELIN	4.0mm	
OSF	MICHELIN	1.0mm	
OSR	MICHELIN	ОК	
Spare	·		

Features

- Bluetooth connection
- PAS

- TASTelephoneDigital radioAir conditioningFront head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Leather seat trim

- Cruise control

- Rear parking sensor Trip computer Body coloured bumpers Climate control
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Tyre pressure monitor Alloy wheels

- Navigation systemRear wiper
- Audio remote control
- Electric door mirrors
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag Central locking

- Park assist camera
- Steering wheel mounted controls
 Auxiliary input socket

- Front fog lights
 Front electric windows
- Rear electric windows
- ABS
- Side airbags Remote central locking

Photos












Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Chipped Multiple Chips



3: Wheel osf Scratched Over 50mm



4: Wing osf Dented Between 10mm + 30mm



5: Door osf Dented Over 30mm



6: Wheel osr Scratched Up To 50mm



7: Qtr Panel osr Dented 2 Or Less UpTo 10mm



8: Bumper Rear Cracked Over 25mm



9: Wheel nsr Scratched Up To 50mm

No Image

10: Wing nsfScratchedOver 25mm Not Thru Paint



11: Wheel nsf Scratched Over 50mm

No Image

12: Tyre osf Less Than 1.6mm Illegal

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	ОК
Sat nav	OK	Steering	OK