



VEHICLE INSPECTION REPORT

GL16FDN

Ford Mondeo 2.0 TDCi EConetic Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/04/2016	Body Style	Hatchback	Last service miles	70,404
Year	2016	Keys	2	MOT Due	28/12/2025
Mileage	131,631 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	3	Doors	5
VIN	WF0EXXWPCEFU18399	Last service date	28/10/2020		

£65 ADDITIONAL FEE.

Last service 28/10/2020 at 70,404 miles- 3 main dealer services Tyre pressure sensor malfunction

One key missing blade

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Corroded
Light



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Dented
Over 30mm



7: Door nsf
Chipped
Edge Chip



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Corroded
Light



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Tailgate
Scratched
UpTo 25mm Thru Paint



13: Wheel osr
Corroded
Light



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Door osr
Scratched
UpTo 25mm Thru Paint



16: Door osf
Chipped
Edge Chip




17: Flasher Side Repeater os
Broken
Replace



18: Wing osf
Scratched
UpTo 25mm Thru Paint



19: Screen Front
Chipped
UpTo 10mm



20: Roof
Chipped
Over 5mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK