



VEHICLE INSPECTION REPORT

WL19NTY

Toyota RAV4 2.5 VVT-i Hybrid Dynamic 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	15/05/2019	Body Style	Estate	Last service miles	54,654
Year	2019	Keys	2	MOT Due	29/07/2026
Mileage	66,806 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Printout	Gears	1
Colour	SILVER	Number of stamps	6		
VIN	JTMRW3FV50J007739	Last service date	09/07/2025		

Last Service - 09.07.2025 at 54654 miles (6 Main dealer services)

Tyres		
NSF	NEXEN	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
 - Navigation system
 - Rear wiper
 - Electric door mirrors
 - Towbar
 - Front armrest
 - Rear electric windows
 - Metallic Paint
 - Drivers airbag
 - Rear airbags
 - Leather seat trim
- Cruise control
 - Park assist camera
 - Steering wheel mounted controls
 - Front fog lights
 - Air conditioning
 - Front electric windows
 - Rear headrests
 - 3x3 point rear seat belts
 - ESP
 - Side airbags
 - Partial leather seat trim
- Front parking sensor
 - PAS
 - Digital radio
 - Roof rails
 - Electrically adjustable drivers seat
 - Front head restraints
 - Steering wheel rake adjustment
 - ABS
 - Isofix child seat anchor points
 - Central locking
 - Alloy wheels
- Heated front seat
 - Rear parking sensor
 - Body coloured bumpers
 - Space saver spare wheel
 - Folding rear seats
 - Height adjustable drivers seat
 - Steering wheel reach adjustment
 - Curtain airbags
 - Passenger airbag
 - Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Dented
Between 10mm + 30mm



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Wheel nsr
Scratched
Up To 50mm



7: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



8: Tailgate
Dented
With Paint Damage



9: Bumper Rear
Dented
Over 30mm



10: Wheel osr
Scratched
Up To 50mm



11: Door osr
Chipped
1 To 5



12: Door osf
Chipped
Edge Chip



13: Flasher Side Repeater os
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK