



VEHICLE INSPECTION REPORT

GD14GYG

Hyundai IX35 1.6 GDI SE 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	07/06/2014	Body Style	Estate	Last service miles	78,738
Year	2014	Keys	1	MOT Due	14/02/2026
Mileage	100,719 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	1		
VIN	TMAJU81ALEJ603990	Last service date	12/01/2024		

Last Service - 12.01.2024 at 78738 miles (1 main dealer services) Oil level warning light is on

Tyres

NSF	BUDGET	4.0mm
NSR	EVENT	5.0mm
OSF	BUDGET	4.0mm
OSR	EVENT	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Remote central locking
- PAS
- Radio/CD
- Full size spare wheel
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsr
Dented
Between 10mm + 30mm



6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Qtr Panel osr
Dented
Over 30mm



8: Door osr
Scratched
UpTo 25mm Thru Paint



9: Wheel osr
Scratched
Over 50mm



10: Door osr
Dented
Between 10mm + 30mm



11: Door osf
Chipped
Edge Chip



12: Wing osf
Chipped
1 To 5



13: Screen Front
Chipped
UpTo 10mm



14: Roof
Scratched
Rusted



15: Seat Base Cover osf
Scuffed
Over 25mm

16: Wing nsf
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK