



VEHICLE INSPECTION REPORT

CF68DZT

Kia Sportage 1.6T GDi ISG 2 5dr [AWD]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/12/2018	Body Style	Estate	Last service miles	39,124
Year	2018	Keys	2	MOT Due	12/11/2025
Mileage	78,213 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	3		
VIN	U5YPH816NKL647279	Last service date	03/11/2021		

£100 ADDITIONAL FEE.

Last Service - 03.11.2021 at 39124 miles (3 main dealer services)

Tyres

NSF	BUDGET	Damaged
NSR	GT RADIAL	6.0mm
OSF	RIKEN	3.0mm
OSR	GT RADIAL	6.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm



4: Door nsf
Dented
Over 30mm



5: Door nsr
Dented
Over 30% Of Panel



6: Wheel nsr
Scratched
Over 50mm



7: Bumper Rear
Scratched
Up To 25mm Thru Paint



8: Tailgate
Scratched
UpTo 25mm Thru Paint



9: Spoiler Rear
Scratched (Painted)
Over 25mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Door osr
Scratched
UpTo 25mm Thru Paint



12: Door osf
Dented
Between 10mm + 30mm



13: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



14: Wheel osf
Scratched
Over 50mm



15: Screen Front
Chipped
UpTo 10mm



16: B Post os
Scratched
Over 25mm Thru Paint



17: Roof
Dented
Over 30mm



18: Tyre nsf
Damaged
Replace



19: B Post ns
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK