



VEHICLE INSPECTION REPORT

GV72BCZ

Toyota Yaris 1.5 Hybrid Design 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	22/12/2022	Body Style	Hatchback	Last service miles	12,760
Year	2022	Keys	2	Gearbox	CVT
Mileage	30,898 Miles Warranted	Service history	Yes	Gears	1
Fuel Type	Hybrid Electric	Service documents	Printout	Doors	5
Colour	BRONZE	Number of stamps	1		
VIN	VNKKBAC310A256650	Last service date	09/02/2024		

£100 ADDITIONAL FEE.

Last service 09/02/2024 at 12,760 miles- 1 service

Tyres

NSF	BUDGET	4.0mm
NSR	CONTINENTAL	2.0mm
OSF	BUDGET	4.0mm
OSR	CONTINENTAL	2.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking
- Park assist camera
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos




1: Bumper Rear
Chipped
Multiple Chips



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




5: Wheel nsr
Scratched
Up To 50mm



6: Door nsr
Dented
2 Or Less UpTo 10mm



7: Door nsf
Chipped
1 To 5



8: Wing nsf
Scratched
Over 25mm Not Thru Paint



9: Wheel nsf
Scratched
Up To 50mm



10: Bonnet
Chipped
1 To 5



11: Bumper Front
Chipped
Multiple Chips



12: Bumper Front
Scratched
Over 25mm Not Thru Paint



13: Wing osf
Chipped
1 To 5



14: Door osf
Dented
Between 10mm + 30mm



15: Door osr
Dented
Over 2 UpTo 10mm



16: Qtr Panel osr
Dented
Over 30mm



17: Wheel osr
Scratched
Up To 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK