



VEHICLE INSPECTION REPORT

KP18HNO

Peugeot 2008 1.6 BlueHDi 100 Active 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/04/2018	Body Style	Hatchback	Last service miles	118,482
Year	2018	Keys	2	MOT Due	28/07/2026
Mileage	126,401 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	3	Doors	5
VIN	VF3CUBHY6JY041285	Last service date	06/06/2025		

£100 ADDITIONAL FEE. Last service 06/06/2025 at 118482 miles (3 services). Book & print.

Tyres

NSF	TRIANGLE	5.0mm
NSR	AVON	5.0mm
OSF	TRIANGLE	5.0mm
OSR	AVON	6.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Digital radio
- Roof rails
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
Over 30mm



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



11: Tailgate
Scratched
UpTo 25mm Thru Paint



12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Chipped
1 To 5



15: Door osf
Scratched
Over 25mm Thru Paint



16: Wing osf
Dented
Over 30mm



17: Wheel osf
Scratched
Over 50mm



18: Roof
Chipped
Over 5mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK