



VEHICLE INSPECTION REPORT

AJ72SDV

Vauxhall Corsa 1.2 Turbo Design 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	09/02/2023	Colour	WHITE	Service history	None
Year	2023	VIN	VXKUPHNEKN4382725	Gearbox	MANUAL
Mileage	20,396 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Petrol	Keys	1	Doors	5

Vehicle hasn't had first MOT.

Tyres

NSF	CONTINENTAL	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint

No Image



3: Wing nsf
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Over 2 UpTo 10mm

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image

7: Door nsr
Scratched
Over 25mm Not Thru Paint

No Image

8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Up To 50mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Boot Lid
Scratched
Over 25mm Not Thru Paint




13: Qtr Panel osr
Dented
Over 30mm



14: Wheel osr
Scratched
Up To 50mm




15: Door osr
Chipped
1 To 5



16: Door osr
Scratched
Over 25mm Not Thru Paint




17: Door osf
Chipped
1 To 5



18: Door osf
Scratched
Over 25mm Not Thru Paint



19: Wing osf
Dented
Between 10mm + 30mm



20: Wing osf
Scratched
Over 25mm Not Thru Paint



21: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK