

# **VEHICLE INSPECTION REPORT**



## Alfa Romeo Mito 0.9 TB TwinAir 105 QV Line 3dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE GRADE
		V5	Present		
Details					
Reg. date	12/05/2015	Body Style	Hatchback	Last service miles	58,272
Year	2015	Keys	2	MOT Due	Expired
Mileage	62,294 Miles Warranted	Service history	Yes	Gearbox	MANUAL
		Service documents	Service Book	Gears	6
Fuel Type	Petrol	Number of stamps	8	Doors	3
Colour	RED	Last service date	22/10/2024		
VIN	ZAR9550000X031657				

### EXPIRED MOT.

Last service 22/10/2024 at 58,272 miles- 8 services (2 main dealer)

Tyres
-------

NSF	BUDGET	3.0mm	
NSR	BUDGET	4.0mm	
OSF	BUDGET	4.0mm	
OSR	BUDGET	4.0mm	
Spare			

## **Features**


- Bluetooth connection
- Steering wheel mounted controls Audio remote control
- Electric door mirrors
- · Front electric windows
- Solid Paint
- · Passenger airbag
- · Alloy wheels
- · Cruise control
- · Air conditioning
- Front head restraints
- Central locking
- PAS
- Radio/CD
- Climate control
- · Height adjustable drivers seat
- Drivers airbagRemote central locking
- · Rear wiper
- Body coloured bumpers
- Front armrest
- Rear headrests
- Isofix child seat anchor points
- · Cloth seat trim

### **Photos**












# **Condition Check**



# **Damage Photos**




1: Bonnet Chipped Multiple Chips



2: Bumper Front Poor Previous Repair Poor Paint



3: Wheel nsf Scratched Over 50mm



4: Wing nsf Chipped 1 To 5



5: Door nsf Chipped 1 To 5

# No Image

6: Door nsf Scratched Over 25mm Not Thru Paint



7: Qtr Panel nsr Dented Over 30mm



8: Wheel nsr Scratched Over 50mm

9: Bumper Rear Chipped Multiple Chips

# No Image

10: Bumper RearScratchedOver 25mm Not Thru Paint



11: Boot Lid Chipped 1 To 5



12: Qtr Panel osr Poor Previous Repair Poor Paint



13: Wheel osr Scratched Over 50mm



14: Door osf Dented Over 30mm



15: Wing osf Poor Previous Repair Poor Paint



16: Wheel osf Scratched Over 50mm

### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

# **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes Or		Clutch Slip Test from Static	OK
Parking Brake OK		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
		, , , , , , , , , , , , , , , , , , ,	
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK