



VEHICLE INSPECTION REPORT

LD66RXP

Volkswagen Golf 1.6 TDI 110 Match Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	22/10/2016	Body Style	Estate	Last service miles	54,143
Year	2016	Keys	2	MOT Due	21/10/2026
Mileage	100,479 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	6		
VIN	WVWZZZAUZHP538702	Last service date	10/03/2022		

Last service 10/03/2022 at 54,143 miles- 6 services (4 main dealer) Engine tapping

Tyres		
NSF	BUDGET	4.0mm
NSR	BRIDGESTONE	2.0mm
OSF	BUDGET	4.0mm
OSR	KUMHO	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Qtr Panel or
Chipped
1 To 5

No Image



3: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

4: Wheel osr
Scratched
Over 50mm



5: Door osr
Chipped
1 To 5

No Image

6: Door osr
Scratched
Over 25mm Not Thru Paint




7: Door osf
Chipped
1 To 5

No Image

8: Door osf
Scratched
Over 25mm Not Thru Paint



9: Wing osf
Scratched
UpTo 25mm Thru Paint



10: Wing osf
Scratched
Over 25mm Not Thru Paint



11: Roof
Chipped
Edge Chip



12: Bonnet
Chipped
Multiple Chips



13: Bumper Front
Poor Previous Repair
Poor Paint



14: Wing nsf
Scratched
Over 25mm Not Thru Paint



15: Wheel nsf
Scratched
Up To 50mm



16: Door nsf
Dented
2 Or Less UpTo 10mm




17: Door nsf
Scratched
Over 25mm Not Thru Paint



18: Door nsf
Scratched
Over 25mm Not Thru Paint



19: Door nsr
Dented
2 Or Less UpTo 10mm



20: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



21: Wheel nsr
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK