

## **VEHICLE INSPECTION REPORT**

FG63KUF

## Kia Sportage 2.0 CRDi KX-3 5dr [Sat Nav]

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		3 GRADE
		V5	Present		
Details					
Reg. date	17/10/2013	Body Style	Estate	Last service miles	81,750
Year	2013	Keys	2	MOT Due	04/03/2026
Mileage	93,960 Miles Warranted	Service history	Yes	Gearbox	MANUAL
		Service documents	Service Book	Gears	6
Fuel Type	Diesel	Number of stamps	6		
Colour	SILVER	Last service date	20/07/2023		
VIN	U5YPC813NDL343511				

£100 ADDITIONAL FEE. Last service 20/07/2023 at 81750 miles (6 services (2 main dealer). Sun roof faulty Steering knocking

Ţ	yre	es
---	-----	----

NSF	PIRELLI	2.0mm	
NSR	PIRELLI	5.0mm	
OSF	PIRELLI	Worn	
OSR	PIRELLI	5.0mm	
Spare			

### **Features**

- Bluetooth connection
- · Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Cruise control
- · Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Real fleadlests
  Passenger airbag
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels


- Navigation system
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Central locking

### **Photos**










# **Condition Check**



## **Damage Photos**



1: Bonnet Chipped Multiple Chips



2: Bumper Front Chipped Over 5mm



3: Wheel nsf Scratched Over 50mm



4: Wing nsf Scratched UpTo 25mm Thru Paint



5: Door nsf Scratched Over 25mm Thru Paint



6: Door nsr Dented Between 10mm + 30mm



7: Wheel osr Scratched Over 50mm



8: Qtr Panel nsr Chipped 1 To 5



9: Tailgate Scratched UpTo 25mm Thru Paint



10: Wheel osr Scratched Over 50mm



11: Qtr Panel osr Dented Between 10mm + 30mm



12: Door osr Scratched Over 25mm Thru Paint



13: Door osf Scratched Over 25mm Thru Paint



14: Wheel osf Scratched Over 50mm



15: Wing osf Chipped 1 To 5



16: Seat Base Cover osf Scuffed Over 25mm

### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

## **Vehicle Inspection Report**

#### Disclaime

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	Fault
Sat nav	OK		