



VEHICLE INSPECTION REPORT

EA66GKX

DS Ds 3 1.6 THP Prestige 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/10/2016	Body Style	Convertible	Last service miles	23,610
Year	2016	Keys	2	MOT Due	28/06/2026
Mileage	32,857 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	5		
VIN	VF7SB5GZMGW566380	Last service date	01/08/2023		

£65 ADDITIONAL FEE

Last service 01/08/2023 at 23,610 miles- 5 services Exhaust blowing
Parking assistance faulty message displayed

Tyres

NSF	KORMORAN	6.0mm
NSR	HANKOOK	5.0mm
OSF	KORMORAN	6.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Digital radio
- Air conditioning
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- PAS
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Rear parking sensor
- Front fog lights
- Height adjustable drivers seat
- Metallic Paint
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Dented
Over 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: B Post os
Dented
Between 10mm + 30mm



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osf
Dented
Over 30mm



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Scratched
UpTo 25mm Thru Paint



16: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK