

VEHICLE INSPECTION REPORT

LC18VRY

Kia Sportage 1.6T GDi GT-Line 5dr DCT Auto [AWD]

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE GRADE
		V5	Present		
Details					
Reg. date	31/05/2018	Body Style	Estate	Last service miles	88,629
Year	2018	Keys	2	MOT Due	30/05/2026
Mileage	90,726 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
		Service documents	Service Book	Gears	7
Fuel Type	Petrol	Number of stamps	9		
Colour	RED	Last service date	07/08/2025		
VIN	U5YPK816WJL500504		-		

Last service 07/08/2025 at 88,629 miles- 9 main dealer services

Tyres

NSF	CONTINENTAL	3.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features

- Bluetooth connection Navigation system

- Rear wiperBody coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls

 Audio remote control

 Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

- · Front parking sensor
- PAS


- · Front head restraints Metallic Paint
- Isofix child seat anchor pointsCentral locking
- · Heated front seat
- Rear parking sensor
- Digital radio Climate control
- Height adjustable drivers seat 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos












Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Poor Previous Repair Poor Paint



3: Wing nsf Chipped 1 To 5



4: Wheel nsf Scratched Over 50mm




5: Door nsf Chipped 1 To 5



6: Door nsr Chipped 1 To 5

No Image





8: Qtr Panel nsr Scratched UpTo 25mm Thru Paint

No Image

9: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



10: Wheel nsr Scratched Over 50mm



11: Bumper Rear Scratched 25 to 100mm Thru Paint

No Image

12: Bumper Rear Scratched Over 25mm Not Thru Paint



13: Boot Lid Chipped 1 To 5



14: Qtr Panel osr Scratched Over 25mm Thru Paint



15: Wheel osr Scratched Over 50mm



16: Door osr Scratched Over 25mm Thru Paint



17: Door osf Chipped 1 To 5



18: Wing osf Chipped 1 To 5



19: Wheel osf Scratched Over 50mm

Interior

Carpet Condition Seat Condition

Average Average **Upholstery Condition Odour**

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK