

VEHICLE INSPECTION REPORT

EJ20JVP

Ford Puma 1.0 EcoBoost Hybrid mHEV ST-Line X First Ed 5dr

| Inspection | | Vehicle | | | nama |
|-----------------|------------------------|-------------------|------------|--------------------|------------|
| Serious Damage? | No | VAT | Margin | | 2 csape |
| | | V5 | Present | | |
| Details | | | | | |
| Reg. date | 24/07/2020 | Body Style | Hatchback | Last service miles | 28,544 |
| Year | 2020 | Keys | 2 | MOT Due | 23/04/2026 |
| Mileage | 34,539 Miles Warranted | Service history | Yes | Gearbox | MANUAL |
| Fuel Type | Petrol | Service documents | Printout | Gears | 6 |
| Colour | BLUE | Number of stamps | 3 | Doors | 5 |
| VIN | WF02XXERK2LB36579 | Last service date | 25/04/2025 | | |

LAST SERVICE 25/4/25 @ 28,544 MILES (3 SERVICES 1 MAIN DEALER) PRINT Front suspension knocking

| Tyres | | | |
|-------|-----------|-------|--|
| NSF | GT RADIAL | 6.0mm | |
| NSR | GT RADIAL | 6.0mm | |
| OSF | GT RADIAL | 6.0mm | |
| OSR | GT RADIAL | 6.0mm | |
| Spare | | | |

Features

- · Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- · Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels

- · Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest Rear electric windows
- **ESP**
- Central locking

Photos










Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Scratched 25 to 100mm Thru Paint



3: Wing nsf Chipped 1 To 5



4: Door nsf Chipped Edge Chip



5: Door nsr Chipped 1 To 5



6: Qtr Panel nsr Chipped 1 To 5



7: Bumper Rear Scratched 25 to 100mm Thru Paint



8: Door osr Chipped 1 To 5



9: Door osf Chipped Edge Chip



10: Wing osf Chipped 1 To 5

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
|--------------------------|----|--|----|
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |