



VEHICLE INSPECTION REPORT

BN64CWZ

Nissan Juke 1.2 DiG-T Acenta Premium 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date	12/09/2014	Body Style	Hatchback	Last service miles	64,980
Year	2014	Keys	2	MOT Due	11/08/2026
Mileage	74,444 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	10	Doors	5
VIN	SJNFEAF15U7013765	Last service date	12/08/2024		

Last service 12/08/2024 at 64,980 miles- 10 services, Book and print Engine misfires

Tyres


NSF	BUDGET	5.0mm
NSR	FIRESTONE	5.0mm
OSF	BUDGET	5.0mm
OSR	FIRESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

Photos





Condition Check




Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Door nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsr
Poor Previous Repair
Poor Paint



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



9: Door osr
Dented
2 Or Less UpTo 10mm



10: Door osf
Scratched
Over 25mm Thru Paint



11: Wing osf
Scratched
UpTo 25mm Thru Paint



12: Roof
Chipped
1 To 5



13: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK		