

VEHICLE INSPECTION REPORT

GY17UGP

Honda HR-V 1.5 i-VTEC EX CVT 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/05/2017	Body Style	Hatchback	Last service miles	76,675
Year	2017	Keys	2	MOT Due	02/05/2026
Mileage	80,837 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Service Book	Gears	1
Colour	BLUE	Number of stamps	7	Doors	5
VIN	3HGRU1890HM301823	Last service date	01/05/2025		

£65 ADDITIONAL FEE

Last service 01/05/2025 at 76,675 miles- 7 main dealer services

Tyres

NSF	MAXXIS	5.0mm	
NSR	NEXEN	5.0mm	
OSF	MAXXIS	5.0mm	
OSR	NEXEN	5.0mm	
Spare			

Features

- Bluetooth connection
- Navigation systemRear wiper
- Electric door mirrors
- Folding rear seatsHeight adjustable drivers seat
- Steering wheel reach adjustment

- Curtain airbagsPassenger airbagRemote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
 Front fog lights
 Front armrest

 Opening panoramic glass roof
 Front electric windows

- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbagsLeather seat trim
- · Front parking sensor
- PAS

- Rear headrests
- 3x3 point rear seat beltsESP

- Side airbagsAlloy wheels

- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
 Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking

Photos










Condition Check



Damage Photos




1: Bonnet Chipped Multiple Chips



2: Bumper Front Scratched 25 to 100mm Thru Paint



3: Wheel nsf Scratched Over 50mm



4: Wing nsf Scratched UpTo 25mm Thru Paint



5: Door nsf Chipped Multiple Chips



6: Door nsr Scratched Over 25mm Thru Paint



7: Wheel nsr Corroded Light



8: Qtr Panel nsr Scratched UpTo 25mm Thru Paint



9: Bumper RearScratched25 to 100mm Thru Paint



10: Tailgate Dented Over 30mm



11: Roof Lining Soiled Light



12: Qtr Panel osr Dented Between 10mm + 30mm



13: Door osr Dented Over 30mm



14: Wheel osr Corroded Light



15: Door osf Chipped Edge Chip



16: Wheel osf Scratched Over 50mm



17: Wing osf Poor Previous Repair Poor Paint

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OK	Gearbox 1st and Reverse Test	OK
Brakes OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	ОК
Windows	OK	Steering	OK
Sat nav	OK		