



VEHICLE INSPECTION REPORT

GU64CRJ

Volkswagen Tiguan 2.0 TDi BlueMotion Tech R-Line 177 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	15/09/2014	Body Style	Estate	Last service miles	100,144
Year	2014	Keys	2	MOT Due	10/08/2026
Mileage	102,059 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Service Book	Gears	7
Colour	GREY	Number of stamps	11		
VIN	WVGZZZ5NZFW027955	Last service date	05/08/2025		

£65 ADDITIONAL FEE. Last service 05/08/2025 at 100144 miles (11 services (6 main dealer). EML light on Keyless system fault

Tyres

NSF	ROYALBLACK	5.0mm
NSR	ROYALBLACK	5.0mm
OSF	ROYALBLACK	5.0mm
OSR	ROYALBLACK	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Digital radio
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Front TowEye Cvr
Missing
Replace



3: Bumper Front
Cracked
Over 25mm



4: Wheel nsf
Scratched
Over 50mm



5: Door osf
Dented
With Paint Damage



6: Door nsr
Dented
2 Or Less UpTo 10mm



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Dented
With Paint Damage



9: Wheel osr
Scratched
Over 50mm



10: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



11: Door osr
Chipped
1 To 5



12: Door osf
Dented
Over 2 UpTo 10mm



13: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		