



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

WO17OPX

Volkswagen Touran 2.0 TDI SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/07/2017	Keys	2	CAP Clean	£10,700.00
Year	2017	Service history	Yes	CAP Average	£9,625.00
Mileage	64,672 Miles Warranted	Service documents	Printout	CAP Below	£8,600.00
Fuel Type	Diesel	Number of stamps	2	Gearbox	MANUAL
Colour	BLUE	Last service date	21/10/2024	Gears	6
VIN	WVGZZZ1TZW113517	Last service miles	59,686		
Body Style	MPV	MOT Due	10/06/2025		

£65 ADDITIONAL FEE. Last Service: 21/10/2024 at 59685 miles. (2 services) Seats Are Stained

Tyres

NSF	GOODYEAR	5.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear headrests
- ESP
- Remote central locking
- PAS
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Dented
Between 10mm + 30mm



2: Wheel osf
Scratched
Over 50mm



3: Door osf
Scratched
Up To 25mm Thru Paint



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
Edge Chip



6: Wheel osr
Scratched
Up To 50mm



7: Bumper Rear
Chipped
Multiple Chips



8: Bumper Rear
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



10: Wheel nsr
Scratched
Up To 50mm



11: Door nsr
Dented
Over 30mm



12: Sill ns
Hole
Over 10mm



13: Door nsf
Chipped
Edge Chip



14: Door nsf
Dented
2 Or Less Up To 10mm



15: Door nsf
Scratched
Over 25mm Not Thru Paint



16: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




17: Wheel nsf
Scratched
Up To 50mm



18: Bumper Front
Scratched
Over 100mm Thru Paint



19: Bonnet
Chipped
1 To 5



20: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK