



VEHICLE INSPECTION REPORT

BG65VOT

Toyota Aygo 1.0 VVT-i X-Cite 2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/10/2015	Body Style	Hatchback	Last service miles	115,498
Year	2015	Keys	2	MOT Due	18/10/2026
Mileage	121,347 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	11	Doors	5
VIN	JTDKGNEC50N107438	Last service date	03/05/2025		

LAST SERVICE 3/5/25 @ 115,498 MILES (11 MAIN DEALER) BOOK

Tyres

NSF	YOKOHAMA	4.0mm
NSR	RIKEN	5.0mm
OSF	YOKOHAMA	4.0mm
OSR	YOKOHAMA	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Insurance telematics
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Dented
2 Or Less UpTo 10mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Poor Previous Repair
Poor Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: A Post ns
Scratched
Over 25mm Thru Paint



7: Door nsf
Chipped
Edge Chip



8: Door nsr
Dented
Over 30mm



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



12: Door osr
Dented
Over 30mm



13: Door osf
Chipped
Edge Chip



14: Screen Front
Chipped
UpTo 10mm



15: Roof
Scratched
Over 25mm Thru Paint

16: Sill ns
Dented
With Paint Damage

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK