



VEHICLE INSPECTION REPORT

PO14RNU

Nissan Qashqai 1.2 DiG-T Acenta Premium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	28/03/2014	Body Style	Hatchback	Last service miles	51,346
Year	2014	Keys	2	MOT Due	06/09/2026
Mileage	84,003 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	4	Doors	5
VIN	SJNFEAJ11U1067703	Last service date	06/09/2021		

£65 ADDITIONAL FEE

Last service 06/09/2021 at 51,346 miles- 4 services (2 main dealer) Osr window fault

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	3.0mm
OSF	FALKEN	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos




1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Boot Lid
Chipped
1 To 5




4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Wheel nsr
Scratched
Over 50mm



6: Door nsr
Scratched
UpTo 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Not Thru Paint



8: Door nsf
Chipped
Multiple Chips

No Image

9: Wing nsf
Chipped
1 To 5



10: Wheel nsf
Scratched
Over 50mm



11: Bonnet
Chipped
Multiple Chips



12: Bumper Front
Chipped
Multiple Chips

No Image

13: Bumper Front
Scratched
Over 25mm Not Thru Paint



14: Wheel osf
Scratched
Over 50mm

No Image

15: Wing osf
Scratched
Over 25mm Not Thru Paint



16: Door osf
Dented
Over 2 UpTo 10mm

No Image

17: Door osf
Scratched
Over 25mm Not Thru Paint



18: Door osr
Chipped
1 To 5

No Image

19: Door osr
Scratched
Over 25mm Not Thru Paint



20: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



21: Wheel osr
Scratched
Over 50mm

22: Roof
Poor Previous Repair
Paint Flake

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	Fault	Steering	OK
Sat nav	OK		