



VEHICLE INSPECTION REPORT

RE68OVG

Hyundai Tucson 1.6 GDi Premium 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	03/12/2018	Body Style	Estate	Last service miles	77,021
Year	2018	Keys	2	MOT Due	07/07/2026
Mileage	80,729 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	8		
VIN	TMAJ3811LKJ761309	Last service date	08/07/2025		

Last service 08/07/2025 at 77021 miles (8 services (4 main dealer)).

Tyres

NSF	CONTINENTAL	Damaged
NSR	NEXEN	6.0mm
OSF	CONTINENTAL	4.0mm
OSR	DAVANTI	7.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Roof rails
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Towbar
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
UpTo 25mm Thru Paint



7: Bumper Rear
Poor Previous Repair
Paint Flake



8: Tailgate
Chipped
1 To 5



9: Qtr Panel osr
Dented
Between 10mm + 30mm



10: Door osr
Dented
Between 10mm + 30mm



11: Door osr
Scratched
UpTo 25mm Thru Paint



12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Wing osf
Chipped
1 To 5



14: Screen Front
Chipped
UpTo 10mm



15: Roof
Scratched
Over 25mm Thru Paint

16: Tyre nsf
Damaged
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK