



VEHICLE INSPECTION REPORT

LV22ZLX

BMW 2 Series 230i M Sport 2dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/08/2022	Body Style	Coupe	Last service miles	17,545
Year	2022	Keys	2	MOT Due	10/06/2026
Mileage	18,895 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Electronic / Online	Gears	8
Colour	MAUVE/PURPLE	Number of stamps	2		
VIN	WBA22CM0008C76632	Last service date	02/06/2025		

£65 ADDITIONAL FEE. Services stored in on-board system.

Last service 02/06/2025 at 17545 miles (2 main dealer services). Osf headlight has condensation

Tyres


NSF	PIRELLI	4.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Audio remote control
- Air conditioning
- Front head restraints
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- Curtain airbags
- Traction control
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag
- Central locking
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Chipped
Edge Chip

No Image




7: Door nsf
Scratched
Over 25mm Not Thru Paint


8: Qtr Panel nsr
Chipped
1 To 5



9: Bumper Front
Chipped
Multiple Chips




10: Bumper Rear
Scratched
Over 25mm Not Thru Paint



11: Boot Lid
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel osr
Chipped
1 To 5




13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



14: Door osf
Chipped
1 To 5

No Image



15: Wing osf
Scratched
Over 25mm Not Thru Paint

16: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK